

FIG. 1




FIG. 2




FIG. 3






FIG. 4




OUTPUT LUMINANCE VALUE

FIG. 5A



OUTPUT LUMINANCE VALUE

FIG. 5B



OUTPUT LUMINANCE VALUE

FIG. 5C




FIG. 6A




FIG. 6B




FIG. 6C





FIG. 7



8/22

FIG. 8




FIG. 9




FIG. 10




FIG. 11A

OUTPUT LUMINANCE VALUE




FIG. 11B

OUTPUT LUMINANCE VALUE




FIG. 12




FIG. 13




FIG. 14




FIG. 15A




FIG. 15B




FIG. 15C




FIG. 16A

TABLE A

		PAST IMAGE							
		NEGATIVE				POSITIVE			
		LU T1	LU T2	LU T3	LU T4	LU T1	LU T2	LU T3	LU T4
CURRENT IMAGE	NEGATIVE	I	I	I	III	II	I	I	III
	POSITIVE	I	II	I	III	I	I	III	I

FIG. 16B

TABLE B

		PAST IMAGE							
		NEGATIVE				POSITIVE			
		LU T1	LU T2	LU T3	LU T4	LU T1	LU T2	LU T3	LU T4
CURRENT IMAGE	NEGATIVE	I	I	III	I	I	II	I	III
	POSITIVE	II	I	I	III	I	I	I	III

FIG. 17

TYPE	CHANGE IN SHADOW	BRIGHTNESS OF SHADOW
A	INCREASE	LOW CONCENTRATION
B	INCREASE	HIGH CONCENTRATION




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22A
PRIOR ART




FIG. 22B
PRIOR ART




FIG. 22C
PRIOR ART




FIG. 22D
PRIOR ART

